

## SAFETY MESSAGE

**Date:** 10/10/2006      **Product:** Siemens Cordaflex SMK 5DH3 4 x 16mm<sup>2</sup> cables

### Concern:

1. Risk of electrical hazard has been identified in deteriorated trailing cable.
2. Inspection of trailing cables on a regular basis to ensure safety of operation recommended.
3. Care urged in manual handling of trailing cables on roof of hoist car, and in general storage conditions.

#### Alimak Hek Pty Ltd

Melbourne - Head Office

2 Ausco Place

Dandenong South, Victoria 3175

Phone +61 3 87956789

Fax +61 3 87956790

Internet: [www.alimakhek.com](http://www.alimakhek.com)

Sydney Office

1 / 264 Miller Road

Villawood, NSW 2163

Phone +61 2 97277425

Fax +61 2 97277475

Brisbane Office

5 / 210 Robinson Road

Geebung, QLD 4034

Phone +61 7 38658188

Fax +61 7 38658488

Perth Office

PO Box 3500

Joondalup WA 6027

Phone +61 8 9300 1946

Fax +61 8 9300 2946